

Projects For 2009 Overlay Program with \$1,000,000.00 Funding

	Geo ID	STREET	BEG LOCATION	END LOCATION	LENGTH	WIDTH	TYPE	LANES	PLAN YR	NOTES
OVERLAY	342	1 LEWIS ST	ROSS Ave	BOWMONT AVE	218	18	BST	2		OPS PRELEVEL, OVERLAY to extend service life, Substand width, complete surfacing failure, pot holes
OVERLAY	239	1 CHURCH ST	N PACIFIC AVE	3RD AVE N	218	28	HMA	2		OPS REPAIR, OVERLAY Surfacing lifted from tree roots, sliding and buckling, dadly weathered
OVERLAY	303	4 GRADE ST	PAV'T CHANGE	CITY LIMITS	806	22	HMA/P CC	2		OPS CRACK SEALING, BR END REPAIRS, HMA over Conc pavement, weathered and cracked pav't
OVERLAY	170	4 ALDER ST	3RD AVE S	4TH AVE S	220	22	HMA	2		POS POT HOLE, CRACK SEAL Extremely weathered and cracked HMA
OVERLAY	341	1 LEWIS ST	N 4TH AVE	ROSS AVE	214	18	BST	2		OPS PRELEVEL, OVERLAY Subs width, drainage prob, weathered HMA, pot holes
OVERLAY	25	1 1ST AVE N	DONATION ST	N PACIFIC AVE	240	33	BST	2	2009	OPS CRACK SEALING, PRELEVEL trans cracks, alligating
OVERLAY	366	3 N 23RD AVE	ALLEN ST	BURCHAM ST	1964	28	HMA	2	2009	OPS REPAIR RUTS PRELEVEL Alligatored/rutted by Church, cracked & dry HMA thru out
OVERLAY	410	5 S 13TH AVE	COLORADO ST	HAZEL ST	1005	32	HMA	3	2011	OPS GRIND CURB, POT HOLE REPAIRED ON 2008 PAV'T PROJECT
OVERLAY	307	4 GRIM RD	W HIGHLAND PK DR	SS of GRIM RD	1005	32	HMA	2	2010	OPS REPAIR SUBG FAILURES, rutting, alligator cracking, utility patches,
OVERLAY	351	2 LORD ST	ES of 9TH AVE N	DEAD END EAST PAV'T WIDENING (Tam'o Lane)	613	18	HMA	2	2009	OPS SHOULDER REPAIRS, recent chip seal, low local traffic volume
OVERLAY	454	4 KELSO DR. W HIGHLAND	COWEEMAN RV BR		1669	45	HMA/Pi	2	2010	OPS BR END REPAIR, POT HOLE REPAIR, CRACK SEALING recent chip seal, parrallel pot holes,
OVERLAY	440	4 PARK DR	DEAD END WEST	PAV'T CHANGE	524	20	BST	2	2010	OPS PRELEVEL, OVERLAY to extend service life, Substand width, surfacing failure, pot holes
OVERLAY	325	2 HOLLY ST	COWLITZ WAY	CLEARVIEW DR	506	15	HMA	1	2009	OPS REPAIR MAJOR FAILURE @ COWLITZ WAY TO EXTEND LIFE, subs width, no storm water control
OVERLAY	37	3 22ND AVE	BLOYD ST	SUNRISE ST	418	20	HMA	2	2009	OPS REPAIR SETTLED AREA'S AT UTILITIES, GRIND GUTTER LINES, very dry HMA, grin
OVERLAY	226	5 CEDAR ST	6TH AVE S	9TH AVE S	239	24	HMA	2	2011	OPS REPAIR POT HOLES, CRACK SEAL TO EXTEND LIFE, storm water issues in this area
OVERLAY	451	1 1ST AVE N	BURCHAM ST	NS DONATION	220	35	HMA	2	2009	OPS CRACK SEAL & CURB GRIND
OVERLAY	430	3 TERESA WAY	MINOR RD	DEAD END NORTI	847	25	BST	2	2011	OPS REPAIR POT HOLES, DIFFERENTIAL SETTLEMENT CRACKING & CURBS
OVERLAY	379	5 OAK ST	S PACIFIC AVE	4TH AVE S	468	33	BST	2	2011	OPS REPAIR RUTTINGEAST OF SO PACIFIC, GRIND CURB LINE
OVERLAY	414	5 S MAPLE ST	S PACIFIC AVE	3RD AVE S	226	36	ACC	2	2011	OPS CRACK SEAL, GRIND CURB LINE GOOD BASE, HMA DRY
OVERLAY	53	2 3RD AVE N	CRAWFORD ST	COLUMBIA ST	229	24	BST	2	2009	OPS GRIND CURB LINE, CRACK SEALING, existing HMA very dry
OVERLAY	165	2 ACADEMY ST	N 4TH AVE	5TH AVE N	236	36	BST	2	2009	OPS CRACK SEAL, GRIND CURB LINE GOOD BASE, HMA DRY

OVERLAY	460	1	1ST AVE N	CHURCH ST	NS of ALLEN ST	518	28	HMA/P CC	2	2009	OPS POT HOLE REPAIR@ CHURCH, low traffic volume
OVERLAY	462	1	DIVISION ST	2ND AVE N	N PACIFIC AVE	823	19			2009	OPS REPAIR POT HOLES,surface good, recent chip seal
OVERLAY	78	2	4TH AVE N	COLUMBIA ST	DEAD END NORTI	242	33	HMA	2	2009	Very low volume 1/2 new HMA, 1/2 severly distressed
OVERLAY	38	3	23RD AVE	BLOYD ST	SUNRISE ST	455	16	HMA	2	2009	OPS CRAK SEAL, GRIND CURDS VERY DRY HMA
OVERLAY	457	4	W HIGHLAND PAF	PAV'T CHANGE	HIGHLAND PARK	194	20			2010	OPS REPAIR FAILED PAV'T TO EXTEND LIFE Alligatored, rough, subs width, open storm drainage
OVERLAY	464	4	GRADE ST	I-5	KELSO DR	374	40			2011	OPS BR END REPAIRS, recent chip seal, trans cracks
OVERLAY	465	4	HIGHLAND PARK	HAUSSLER RD	W HIGHLAND PK :	1107	20			2010	OPS REPAIR FAILED PAV'T TO EXTEND LIFE Alligatored, rough, subs width, open storm drainage
OVERLAY	466	4	KELSO DR.	PAV'T WIDENING	ALLEN ST					2010	surface fair, cracking, patches
OVERLAY	456	5	RIVERSIDE DR	RIVER RD	RR TRACKS	1771	18			2011	OPS REPAIR PAV'T FAILURE TO EXTEND LIFE, surface poor, HMA dry, lots pot holes, LOW VOLUME
OVERLAY	463	5	GRADE ST	COWEEMAN RV BR	I-5	730	40			2011	OPS BR END REPAIRS, recent chip seal, trans cracks
OVERLAY	439	4	VISTA WAY	W VISTA WAY	DEAD END NORTI	998	20	ACC	1	2010	RECENT UTIL WORK HAS REPLACED MOST OF RD